

CLASSIFIED MESSAGE

DATE 0015Z 15 SEP 62

SECRET

1	4
2	5
3	6

TO DIRECTOR

FROM [REDACTED] 25X1A

ACTION: OPS (1-2-3-4-5)

INFO : S/C (6)

PRIORITY

PRIORITY

TOR: 0114Z 15 SEP 62 25X1A

IN: 48758

TO PRITY [REDACTED] 25X1A

INFO [REDACTED]

25X1A

CITE

054

25X1A [REDACTED] NIMBUS 25X1A

REF: [REDACTED] 6502 (OUT 28303) 25X1A 25X1A

25X1A

A. T-33 [REDACTED] ARR [REDACTED] 14/2230Z WITH [REDACTED]

B. PAR 3 REF MSG, DO NOT RECOMMEND CUTTING AND REWINDING

SINCE FACILITIES NOT AVAIL TO ACCOMP AND ALSO PRESENTS A PROBELM OF PLACING BALLAST IN NOSE OF ARTICLE FOR PROPER CG. *OK*

TIME FOR PROCESSING SHOULD NOT BE EFFECTED UNDER PRESENT

PROCEDURES HOWEVER, SINCE ONLY EXPOSED PORTION OF [REDACTED] PLUS A FEW FRAMES ON EACH END FOR PREFLIGHT ETC IS BEING SENT

25X1A

TO [REDACTED]

C. PAR 4 REF MSG, NORMAL PROCEDURES DO NOT REQUIRE TURNING

OFF AC GEN [REDACTED] TURN OFF IS ACCOMP ONLY WHEN

ENG POWER IS REDUCED BELOW [REDACTED] DESCENT TO MAX RANGE *OK*

CRUISE IS NORMALLY ACCOMP AT [REDACTED] WITH SUBJ EQUIP ON. 25X1A

THE EARLY TURN OFF MSN 3089 WHICH WAS REFLECTED ON THE ROUGH

OVERLAY AND OCCURRED APPROX 5 MIN WEST OF 90 DEG WEST WAS

25X1A

DUE TO POWER REDUCTION BELOW [REDACTED] TO

SECRET

GROUP I
EXCLUDED FROM AUTOMATIC
DOWNGRADING AND
DECLASSIFICATION

25X1A

S E C R E T

[] 054 IN 48758)

PAGE TWO

CONSERVE ADDITIONAL FUEL. WE DO NOT ANTICIPATE THAT THIS WILL BE A COMMON OCCURRENCE. AT ANY TIME THIS EQUIP IS TURNED OFF AND/OR ON AGAIN, COMMENTS WILL BE MADE IN THE [] AND WILL BE REFLECTED ON THE OVERLAYS.

25X1A

END OF MESSAGE

S E C R E T